


**BLOWER MOTOR ASSEMBLY NOISE (Continued)**



PC0010-1A-F-RP

Figure 15 – Blower Motor Assembly Noise Diagnostic Procedure (2 of 2)